

Material Thickness vs. Maximum OAH for rolled parts in Small Roll & Weld Cell

Note: If there are one or two flanges or beads, the max OAH of the part will decrease the sum of the widths of each flange and or arc length of the bead

